

Water Testing Results - Administration Building
Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Room #	Fixture ID #	Date Tested	
North Womens Restroom Left Faucet	29	21080000-001BF23A	2/14/2023	1.33
North Womens Restroom Right Faucet	29	21080000-002BF23A	2/14/2023	1.36
North Mens Restroom Left Faucet	30	21080000-003BF23A	2/14/2023	2.44
North Mens Restroom Right Faucet	30	21080000-004BF23A	2/14/2023	ND
Kitchen Faucet	31	21080000-005KF23A	2/14/2023	1.67
North Drinking Fountain	31	21080000-006WB23A	2/14/2023	ND
Centrally Located Restroom Faucet	34	21080000-007BF23A	2/14/2023	ND
West Mens Restroom Faucet	36	21080000-008BF23A	2/14/2023	2.92
West Womens Restroom Faucet	37	21080000-009BF23A	2/14/2023	ND
South Basement Staff Faucet	62	21080000-011KF23A	2/14/2023	9.5
South Basement Restroom Faucet	64	21080000-012BF23A	2/14/2023	15.2
Any fixture testing at or above the action level of 15 ppb is immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up testing				
RETESTS				
South Basement Restroom Faucet	64	21080000-012BF23B	4/4/2023	3.02

ND = Non Detect - Lead level is below the set detection limits of 1 ppb