

Water Testing Results - Aiken Elementary

Action Level is 15 parts per billion (ppb)

| Fixture Location/Description | Room # | Fixture ID # | Date Tested | |
|----------------------------------|--------|-------------------|-------------|----------|
| Classroom 101 Faucet | 101 | 21080100-001CF23A | 2/28/2023 | ND |
| Classroom 101 Drinking Fountain | 101 | 21080100-002DW23A | 2/28/2023 | ND |
| Classroom 102 Faucet | 102 | 21080100-003CF23A | 2/28/2023 | 1.66 ppb |
| Classroom 102 Drinking Fountain | 102 | 21080100-004DW23A | 2/28/2023 | ND |
| West Girls Restroom Left Faucet | 104 | 21080100-005BF23A | 2/28/2023 | ND |
| West Girls Restroom Right Faucet | 104 | 21080100-006BF23A | 2/28/2023 | ND |
| West Boys Restroom Left Faucet | 106 | 21080100-007BF23A | 2/28/2023 | ND |
| West Boys Restroom Right Faucet | 106 | 21080100-008BF23A | 2/28/2023 | 1.51 ppb |
| Classroom 1 Faucet | 1 | 21080100-009CF23A | 2/28/2023 | 6.03 ppb |
| Classroom 1 Drinking Fountain | 1 | 21080100-010DW23A | 2/28/2023 | 3.93 ppb |
| Classroom 2 Faucet | 2 | 21080100-011CF23A | 2/28/2023 | 5.92 ppb |
| Classroom 2 Drinking Fountain | 2 | 21080100-012DW23A | 2/28/2023 | 10.2 ppb |
| Classroomm 3 Faucet | 3 | 21080100-013CF23A | 2/28/2023 | 4.61 ppb |
| Classroom 3 Drinking Fountain | 3 | 21080100-014DW23A | 2/28/2023 | 7.64 ppb |
| Classroom 4 Faucet | 4 | 21080100-015CF23A | 2/28/2023 | 4.87 ppb |
| Classroom 4 Drinking Fountain | 4 | 21080100-016DW23A | 2/28/2023 | 7.23 ppb |
| NW Boys Restroom Faucet | 38 | 21080100-017BF23A | 2/28/2023 | 4.61 ppb |
| NW Girls Restroom Faucet | 39 | 21080100-018BF23A | 2/28/2023 | 4.11 ppb |
| North Storage Room Faucet | 17 | 21080100-019KF23A | 2/28/2023 | ND |
| Gym Drinking Fountain | 18 | 21080100-020WB23A | 2/28/2023 | ND |
| North Staff Restroom Faucet | 20 | 21080100-021OT23A | 2/28/2023 | 5.41 ppb |
| Break Room Faucet | 25 | 21080100-022KF23A | 2/28/2023 | 4.10 ppb |
| Work Room Faucet | 25 | 21080100-023SF23A | 2/28/2023 | 5.84 ppb |
| Office Womens Restroom Faucet | 34 | 21080100-024BF23A | 2/28/2023 | 3.88 ppb |
| Office Mens Restroom Faucet | 35 | 21080100-025BF23A | 2/28/2023 | 3.98 ppb |
| Classroom 5 Faucet | 5 | 21080100-026CF23A | 2/28/2023 | 2.32 ppb |
| Classroom 5 Drinking Fountain | 5 | 21080100-027DW23A | 2/28/2023 | 3.99 ppb |
| Classroom 7 Faucet | 7 | 21080100-028CF23A | 2/28/2023 | 5.08 ppb |
| Classroom 7 Drinking Fountain | 7 | 21080100-029DW23A | 2/28/2023 | 19.5 ppb |
| East Boys Restroom Faucet | 32 | 21080100-030BF23A | 2/28/2023 | 3.63 ppb |

| | | | | |
|--|----|-------------------|-----------|----------|
| East Girls Restroom Faucet | 33 | 21080100-031BF23A | 2/28/2023 | 2.11 ppb |
| Classroom 9 Faucet | 9 | 21080100-032CF23A | 2/28/2023 | 3.22 ppb |
| Classroom 9 Drinking Fountain | 9 | 21080100-033DW23A | 2/28/2023 | 2.77 ppb |
| Classroom 10 Faucet | 10 | 21080100-034CF23A | 2/28/2023 | 9.2 ppb |
| Classroom 10 Drinking Fountain | 10 | 21080100-035DW23A | 2/28/2023 | 9.75 ppb |
| Classroom 11 Faucet | 11 | 21080100-036CF23A | 2/28/2023 | 1.12 ppb |
| Classroom 11 Drinking Fountain | 11 | 21080100-037DW23A | 2/28/2023 | 8.18 ppb |
| Classroom 12 Faucet | 12 | 21080100-038CF23A | 2/28/2023 | 3.07 ppb |
| Classroom 12 Drinking Fountain | 12 | 21080100-039DW23A | 2/28/2023 | 7.50 ppb |
| East Boys Restroom Faucet | 30 | 21080100-040BF23A | 2/28/2023 | 2.67 ppb |
| East Girls Restroom Faucet | 31 | 21080100-041BF23A | 2/28/2023 | 1.63 ppb |
| Any fixture testing at or above the action level of 15 ppb is immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up testing | | | | |
| RETESTS | | | | |
| Classroom 7 Drinking Fountain | 7 | 21080100-029DW23B | 4/4/2023 | 4.99 |
| | | | | |
| ND = Non Detect - Lead level is below the set detection limits of 1 ppb | | | | |