

Water Testing Results - Aiken Elementary

Action Level is 15 parts ber billion (ppb)

Fixture Location/Description	Room #	Fixture ID #	Date Tested	
Classroom 101 Faucet	101	21080100-001CF23A	2/28/2023	ND
Classroom 101 Drinking Fountain	101	21080100-002DW23A	2/28/2023	ND
Classroom 102 Faucet	102	21080100-003CF23A	2/28/2023	1.66 ppb
Classroom 102 Drinking Fountain	102	21080100-004DW23A	2/28/2023	ND
West Girls Restroom Left Faucet	104	21080100-005BF23A	2/28/2023	ND
West Girls Restroom Right Faucet	104	21080100-006BF23A	2/28/2023	ND
West Boys Restroom Left Faucet	106	21080100-007BF23A	2/28/2023	ND
West Boys Restroom Right Faucet	106	21080100-008BF23A	2/28/2023	1.51 ppb
Classroom 1 Faucet	1	21080100-009CF23A	2/28/2023	6.03 ppb
Classroom 1 Drinking Fountain	1	21080100-010DW23A	2/28/2023	3.93 ppb
Classroom 2 Faucet	2	21080100-011CF23A	2/28/2023	5.92 ppb
Classroom 2 Drinking Fountain	2	21080100-012DW23A	2/28/2023	10.2 ppb
Classroomm 3 Faucet	3	21080100-013CF23A	2/28/2023	4.61 ppb
Classroom 3 Drinking Fountain	3	21080100-014DW23A	2/28/2023	7.64 ppb
Classroom 4 Faucet	4	21080100-015CF23A	2/28/2023	4.87 ppb
Classroom 4 Drinking Fountain	4	21080100-016DW23A	2/28/2023	7.23 ppb
NW Boys Restroom Faucet	38	21080100-017BF23A	2/28/2023	4.61 ppb
NW Girls Restroom Faucet	39	21080100-018BF23A	2/28/2023	4.11 ppb
North Storage Room Faucet	17	21080100-019KF23A	2/28/2023	ND
Gym Drinking Fountain	18	21080100-020WB23A	2/28/2023	ND
North Staff Restroom Faucet	20	21080100-021OT23A	2/28/2023	5.41 ppb
Break Room Faucet	25	21080100-022KF23A	2/28/2023	4.10 ppb
Work Room Faucet	25	21080100-023SF23A	2/28/2023	5.84 ppb
Office Womens Restroom Faucet	34	21080100-024BF23A	2/28/2023	3.88 ppb
Office Mens Restroom Faucet	35	21080100-025BF23A	2/28/2023	3.98 ppb
Classroom 5 Faucet	5	21080100-026CF23A	2/28/2023	2.32 ppb
Classroom 5 Drinking Fountain	5	21080100-027DW23A	2/28/2023	3.99 ppb
Classroom 7 Faucet	7	21080100-028CF23A	2/28/2023	5.08 ppb
Classroom 7 Drinking Fountain	7	21080100-029DW23A	2/28/2023	19.5 ppb
East Boys Restroom Faucet	32	21080100-030BF23A	2/28/2023	3.63 ppb

East Girls Restroom Faucet	33	21080100-031BF23A	2/28/2023	2.11 ppb
Classroom 9 Faucet	9	21080100-032CF23A	2/28/2023	3.22 ppb
Classroom 9 Drinking Fountain	9	21080100-033DW23A	2/28/2023	2.77 ppb
Classroom 10 Faucet	10	21080100-034CF23A	2/28/2023	9.2 ppb
Classroom 10 Drinking Fountain	10	21080100-035DW23A	2/28/2023	9.75 ppb
Classroom 11 Faucet	11	21080100-036CF23A	2/28/2023	1.12 ppb
Classroom 11 Drinking Fountain	11	21080100-037DW23A	2/28/2023	8.18 ppb
Classroom 12 Faucet	12	21080100-038CF23A	2/28/2023	3.07 ppb
Classroom 12 Drinking Fountain	12	21080100-039DW23A	2/28/2023	7.50 ppb
East Boys Restroom Faucet	30	21080100-040BF23A	2/28/2023	2.67 ppb
East Girls Restroom Faucet	31	21080100-041BF23A	2/28/2023	1.63 ppb
Any fixture testing at or above the action level of 15 ppb is immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up testing				
RETESTS				
Classroom 7 Drinking Fountain	7	21080100-029DW23B	4/4/2023	4.99
ND = Non Detect - Lead level is below the set detection limits of 1 ppb				