



## Safety Inspection Report

Date: 5/12/14 Location: Alternative school

### Details of Inspection:

1. Everything looks good
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

### Responsible Party

- |    |       |
|----|-------|
| 1. | _____ |
| 2. | _____ |
| 3. | _____ |
| 4. | _____ |
| 5. | _____ |
| 6. | _____ |
| 7. | _____ |
| 8. | _____ |

Jessamine K. Wyborny  
Signature of Building  
Representative

Bob Bennett  
Inspector

\_\_\_\_\_  
Signature of Administrator

\_\_\_\_\_  
Date of Compliance



# Safety Inspection Report

Date: 5-14-14 Location: OHS

### Details of Inspection:

1. Library <sup>ATV</sup> COPY Room <sup>vacuum cleaner</sup> Paper role Cart in walkway
2. Paper Role Cart And vacuum cleaner in walkway
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

### Responsible Party

1. Keep walk way clear - OK
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

Luis Durr  
Signature of Building Representative

Jede Leon  
Signature of Administrator

Antonio  
Inspector

5/14/14  
Date of Compliance



# Safety Inspection Report

Date: 5/14/14 Location: Pioneer

### Details of Inspection:

- 1. <sup>SP. Ed,</sup> ~~SP. Ed,~~ - Computer Wires loose & ~~SP. Ed,~~ 76
- 10S. Resource Room - Partition lo' not attached &
- 3. Clearance for walkway to East Exit door
- 4. \_\_\_\_\_
- 5. \_\_\_\_\_
- 6. \_\_\_\_\_
- 7. \_\_\_\_\_
- 8. \_\_\_\_\_

### Recommendations:

### Responsible Party

- 1. \_\_\_\_\_
- 2. \_\_\_\_\_
- 3. \_\_\_\_\_
- 4. \_\_\_\_\_
- 5. \_\_\_\_\_
- 6. \_\_\_\_\_
- 7. \_\_\_\_\_
- 8. \_\_\_\_\_

\_\_\_\_\_  
Signature of Building Representative

Paula Duesch  
Inspector

J. Davis  
Signature of Administrator

5/14/14  
Date of Compliance



## Safety Inspection Report

Date: 5/19/14 Location: Cairo

### Details of Inspection:

1. Missroom
2. Fire Extinguisher
3. Library
4. Cafeteria
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

- | Recommendations:          | Responsible Party |
|---------------------------|-------------------|
| 1. <u>look great</u>      | _____             |
| 2. <u>up to date good</u> | _____             |
| 3. <u>looks good</u>      | _____             |
| 4. <u>great</u>           | _____             |
| 5. _____                  | _____             |
| 6. _____                  | _____             |
| 7. _____                  | _____             |
| 8. _____                  | _____             |

Kathleen Dunto  
Signature of Building  
Representative

Melanie Gering  
Inspector

\_\_\_\_\_  
Signature of Administrator

5/19/14  
Date of Compliance



# Safety Inspection Report

Date: 5-20-14 Location: Alameda

### Details of Inspection:

1. EVERYTHING LOOKS OKAY
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

### Responsible Party

- |    |       |
|----|-------|
| 1. | _____ |
| 2. | _____ |
| 3. | _____ |
| 4. | _____ |
| 5. | _____ |
| 6. | _____ |
| 7. | _____ |
| 8. | _____ |

Karen Fisher  
Signature of Building Representative

Daniel K. Wood  
Inspector

\_\_\_\_\_  
Signature of Administrator

\_\_\_\_\_  
Date of Compliance



## Safety Inspection Report

Date: 5/20/14 Location: Bus Shop


### Details of Inspection:


1. Looks good! Very organized
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

### Responsible Party

- |    |       |
|----|-------|
| 1. | _____ |
| 2. | _____ |
| 3. | _____ |
| 4. | _____ |
| 5. | _____ |
| 6. | _____ |
| 7. | _____ |
| 8. | _____ |

  
Signature of Building  
Representative

  
Inspector

\_\_\_\_\_  
Signature of Administrator

\_\_\_\_\_  
Date of Compliance



## Safety Inspection Report

Date: 05/22/14 Location: Warehouse

### Details of Inspection:

1. walked throughout building.
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

- |   | Responsible Party |
|---|-------------------|
| 1. <u>Could use more space for tools,</u> | _____             |
| 2. _____                                  | _____             |
| 3. _____                                  | _____             |
| 4. _____                                  | _____             |
| 5. _____                                  | _____             |
| 6. _____                                  | _____             |
| 7. _____                                  | _____             |
| 8. _____                                  | _____             |

[Signature]  
Signature of Building  
Representative

[Signature]  
Inspector

\_\_\_\_\_  
Signature of Administrator

5/22/14  
Date of Compliance



## Safety Inspection Report

Date: 5-23-14 Location: Aiken

### Details of Inspection:

1. Everything looks good Tom!
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

### Responsible Party

- | Recommendations:    | Responsible Party |
|---------------------|-------------------|
| 1. <u>Kipper up</u> | _____             |
| 2. _____            | _____             |
| 3. _____            | _____             |
| 4. _____            | _____             |
| 5. _____            | _____             |
| 6. _____            | _____             |
| 7. _____            | _____             |
| 8. _____            | _____             |

[Signature]  
Signature of Building  
Representative

[Signature]  
Inspector

Date of Compliance \_\_\_\_\_





## Safety Inspection Report

Date: May 27, 2014 Location: OMS


### Details of Inspection:


1. Looks Good!
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_


### Recommendations:

1. \_\_\_\_\_
2. None
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Responsible Party

  
\_\_\_\_\_  
Signature of Building  
Representative

  
\_\_\_\_\_  
Signature of Administrator

  
\_\_\_\_\_  
Inspector

NA  
\_\_\_\_\_  
Date of Compliance



## Safety Inspection Report


Date: 5/27/14 Location: DISTRICT

### Details of Inspection:

1. FIRE EXTINGUISHER IN THE BASEMENT.
2. FIRE EXTINGUISHER BOARD ROOM
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

- |                                 | Responsible Party |
|---------------------------------|-------------------|
| 1. <u>NEEDS TO BE INSPECTED</u> | <u>CUSTODIAN</u>  |
| 2. <u>NEEDS TO BE INSPECTED</u> | <u>CUSTODIAN</u>  |
| 3. _____                        | _____             |
| 4. _____                        | _____             |
| 5. _____                        | _____             |
| 6. _____                        | _____             |
| 7. _____                        | _____             |
| 8. _____                        | _____             |

  
\_\_\_\_\_  
Signature of Building  
Representative

ALBERTO DIAZ  
\_\_\_\_\_  
Inspector

\_\_\_\_\_  
Signature of Administrator

\_\_\_\_\_  
Date of Compliance