



Safety Inspection Report

Date: 4/4/17 Location: Mary Roberts

Details of Inspection:

1. gravel from playground covering front sidewalk.
2. loading dock needs painted stripes
3. gravel needs raked back under swings.
4. 100 Hall custodial closet has things stored in front of + on
5. electrical panels
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. Sweep or blow it back into playground.
2. maintenance work order.
3. Custodial
4. custodial needs to make corrections
5. _____
6. _____
7. _____
8. _____

Maria Benites
Signature of Building
Representative

Rob Bennett
Inspector

Signature of Administrator

Date of Compliance



Safety Inspection Report

Date: 4/12/13 Location: Warehouse


Details of Inspection:


1. In good order - very nice!
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____


Signature of Building
Representative


Inspector


Signature of Administrator

4-12-13
Date of Compliance



Safety Inspection Report

Date: 4/12/ Location: Cairo

Details of Inspection:

1. Everything looks great!!
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Denise Duval
Signature of Building
Representative

Laurie Duval
Inspector

Signature of Administrator

Date of Compliance



Safety Inspection Report

Date: 4/22/13 Location: OMS


Details of Inspection:


1. Music Stands Stacked-up Above
2. A Dresser
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. ASK music teacher how often ten-
2. are been used & how he gets them down
3. _____
4. _____ Music Teacher
5. _____
6. _____
7. _____
8. _____


Signature of Building
Representative


Inspector

Signature of Administrator

Date of Compliance



Safety Inspection Report

Date: 4-23-13 Location: OHS


Details of Inspection:

- | | | |
|----|--------------------------|------|
| 1. | Athletic Director Office | Good |
| 2. | Comp. Lab | Good |
| 3. | Cafeteria | Good |
| 4. | Wood Shop | Good |
| 5. | Mechanic Shop (ACG) | |
| 6. | Auto Shop | |
| 7. | | |
| 8. | | |

Recommendations:

Responsible Party

- | | | |
|----|-----------|--|
| 1. | | |
| 2. | Auto Shop | - Remove Trash Cans from around electrical boxes |
| 3. | | |
| 4. | | |
| 5. | | |
| 6. | | |
| 7. | | |
| 8. | | |


Signature of Building
Representative


Inspector

Date of Compliance 4/24/13



Safety Inspection Report

Date: 11-04-13 Location: Flameless

Details of Inspection:

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. _____
2. Mike
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

[Signature]
Signature of Building
Representative

[Signature]
Inspector

[Signature]
Signature of Administrator

11-04-13
Date of Compliance



Safety Inspection Report

Date: 4/24/13 Location: District Office

Details of Inspection:

1. Good - Didn't find anything
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

- | | |
|----|-------|
| 1. | _____ |
| 2. | _____ |
| 3. | _____ |
| 4. | _____ |
| 5. | _____ |
| 6. | _____ |
| 7. | _____ |
| 8. | _____ |


Signature of Building
Representative


Inspector


Signature of Administrator

4-24-13
Date of Compliance



Safety Inspection Report

Date: 4-25-2013 Location: ALT School

Details of Inspection:

1. FIRE Extinguisher need to be updated.
2. _____
3. Everything else looks good.
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

- | | Responsible Party |
|--------------------------------------|-------------------|
| 1. <u>Monthly inspection needed.</u> | _____ |
| 2. _____ | _____ |
| 3. _____ | _____ |
| 4. _____ | _____ |
| 5. _____ | _____ |
| 6. _____ | _____ |
| 7. _____ | _____ |
| 8. _____ | _____ |

Lynne Baskin

Signature of Building
Representative

ALBERTO DIAZ

Inspector

Signature of Administrator

Date of Compliance



Safety Inspection Report

Date: 4-25-13 Location: PIONEER SCHOOL

Details of Inspection:

1. Baseball Backstop - Rotten POST leaning over
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. Replace POST
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Jay Rhodes
Signature of Building
Representative

Antonie Coronea
Inspector

Signature of Administrator

Date of Compliance