



Safety Inspection Report

Date: 2/12/14 Location: Pioneer School

Details of Inspection:

1. fire extinguisher inspection for February NOT Done
2. The PIC OFFICE SPACE heater cord in the walk way
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. See inspection
2. move it to the wall
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Martin Davila
Signature of Building
Representative

Antonio Corrao
Inspector

Jayne Rhodes
Signature of Administrator

Date of Compliance



Safety Inspection Report

Date: 2-14-14 Location: Warehouse

Details of Inspection:

1. everything looks okay
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

BB
Signature of Building
Representative

MMA Under
Inspector

Bob Bennett
Signature of Administrator

2/14/14
Date of Compliance



Safety Inspection Report

Date: 2/18/14 Location: Aiken

Details of Inspection:

1. Looks Good!!
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Shelley Jensen
Signature of Building
Representative

Danir Dues
Inspector

Quin Baulidg
Signature of Administrator

2-18-14
Date of Compliance



Safety Inspection Report

Date: 2/19/14 Location: District Office

Details of Inspection:


1. Everything looks good to me
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. Kip-up
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____


Signature of Building
Representative


Inspector


Signature of Administrator

Date of Compliance



Safety Inspection Report

Date: 2/19/11 Location: May Roberts

Details of Inspection:

1. As winter leaves we need to get the rock off of
2. sidewalk & back into the south playground
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. Sweep or blow rock off sidewalks & asphalt & curbside
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Man'a Benites
Signature of Building
Representative

BB
Inspector

Signature of Administrator

Date of Compliance



Safety Inspection Report

Date: 2-20-14 Location: Bus Shop

Details of Inspection:


1. _____
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____


Recommendations:

Responsible Party

1. Bus shop - mechanic room, look-great
2. Staff room - great
3. Bus parking Area - good
4. _____
5. _____
6. _____
7. _____
8. _____

Signature of Building
Representative


Signature of Administrator


Inspector

2-20-14
Date of Compliance



Safety Inspection Report

Date: 2-24-14 Location: Cairo

Details of Inspection:

- | | | |
|----|-------------------|-----------------|
| 1. | Cafeteria - OK | Playground - OK |
| 2. | Library - OK | |
| 3. | Computer Lab - OK | |
| 4. | Staff Room - OK | |
| 5. | Classroom 5 - OK | |
| 6. | 1 - 4 - OK | |
| 7. | 3 - OK | |
| 8. | Kindergarten - OK | |

Recommendations:

Responsible Party

- | | | |
|----|----------------|--|
| 1. | Looks Great!!! | |
| 2. | | |
| 3. | | |
| 4. | | |
| 5. | | |
| 6. | | |
| 7. | | |
| 8. | | |

Vivian Shaw
Signature of Building
Representative

Diana Burnett
Inspector

Kathleen Dunstan
Signature of Administrator

2/24/14
Date of Compliance



Safety Inspection Report

Date: 2-26-14 Location: Alameda

Details of Inspection:

1. Fan in front of electrical panel
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

- | | Responsible Party |
|------------------|-------------------|
| 1. <u>Remove</u> | <u>Custodian</u> |
| 2. _____ | _____ |
| 3. _____ | _____ |
| 4. _____ | _____ |
| 5. _____ | _____ |
| 6. _____ | _____ |
| 7. _____ | _____ |
| 8. _____ | _____ |

[Signature]
Signature of Building
Representative

[Signature]
Signature of Administrator

[Signature]
Inspector

2-26-14
Date of Compliance



Safety Inspection Report

Date: Feb. 26, 2014 Location: alt. school (OHS)

Details of Inspection:

1. Awesome Building!
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. None
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

John William Boyd
Signature of Building
Representative

Deise Quaid
Inspector

Signature of Administrator

Date of Compliance



Safety Inspection Report

Date: 2/26/14 Location: Ontario High

Details of Inspection:

1. Looked at Office + 2 classes.
2. _____
3. _____
4. Nothing sticking out!
5. _____
6. _____
7. _____
8. _____

Recommendations:

1. Keep up the good work!
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Responsible Party

[Signature]
Signature of Building
Representative

[Signature]
Inspector

[Signature]
Signature of Administrator

2/26/14
Date of Compliance



Safety Inspection Report

Date: 2/26/14 Location: OMS

Details of Inspection:


1. Room 101 looks good
2. Room 102 cords hanging down the table
3. Fire Ext. good
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. _____
2. Room 102 Tidy the cords behind the tables
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____


Signature of Building
Representative


Inspector

Signature of Administrator

Date of Compliance