



## Safety Inspection Report

Date: 1/7/14 Location: ALT school

### Details of Inspection:

1. EXTINGUISHER NED chequin The Days
2.
3. The rest looks good
4.
5.
6.
7.
8.

| Recommendations:                              | Responsible Party |
|-----------------------------------------------|-------------------|
| 1. <u>CUSTODIAN</u><br><u>Check Abit Mant</u> | <u>Teachers</u>   |
| 2. <u></u>                                    | <u></u>           |
| 3. <u>Kipper AP</u>                           | <u></u>           |
| 4. <u></u>                                    | <u></u>           |
| 5. <u></u>                                    | <u></u>           |
| 6. <u></u>                                    | <u></u>           |
| 7. <u></u>                                    | <u></u>           |
| 8. <u></u>                                    | <u></u>           |

Jobi William Boyd  
Signature of Building  
Representative

matin Darab  
Inspector

[Signature]  
Signature of Administrator

1-7-14  
Date of Compliance



## Safety Inspection Report

Date: 1-14-14 Location: CAIRO

### Details of Inspection:

1. IT IS A LITTLE SLICK OUTSIDE IN SOME PLACES
2. BUT NOT TOO BAD.
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

### Responsible Party

1. KEEP USING DE-ICER
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

Denise Quaid

Signature of Building  
Representative

Antonio Corona  
Inspector

[Signature]  
Signature of Administrator

1/14/14  
Date of Compliance



## Safety Inspection Report

Date: 1/14/14 Location: Pioneer

### Details of Inspection:

1. Entry mats need to be up next to the door.
2. Nice sign warning of ice.
3. Very nice & CLEAN dry sidewalks.
4. check to see if upstairs hall exit lights are working.
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

### Responsible Party

1. move mats in closer to entries in gym. custodian
2. \_\_\_\_\_
3. \_\_\_\_\_
4. Push test buttons and see if they stay lit. custodian
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

Jaye Rhodes  
Signature of Building  
Representative

BB  
Inspector

\_\_\_\_\_  
Signature of Administrator

\_\_\_\_\_  
Date of Compliance



## Safety Inspection Report

Date: 1/17/14 Location: Bus Shop

### Details of Inspection:

1. Looks Good!!
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

### Responsible Party

1. \_\_\_\_\_
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

Carlos Nelson  
Signature of Building  
Representative

Frankie Duesch  
Inspector

\_\_\_\_\_  
Signature of Administrator

\_\_\_\_\_  
Date of Compliance



## Safety Inspection Report

Date: 1/17/14 Location: OH3

### Details of Inspection:

1. Looked around Main Hall & New Wing (looks Good)!!
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

### Responsible Party

- |    |       |
|----|-------|
| 1. | _____ |
| 2. | _____ |
| 3. | _____ |
| 4. | _____ |
| 5. | _____ |
| 6. | _____ |
| 7. | _____ |
| 8. | _____ |

Signature of Building  
Representative

Inspector

\_\_\_\_\_  
Signature of Administrator

\_\_\_\_\_  
Date of Compliance



## Safety Inspection Report

Date: 1-17-14 Location: DISTRICT OFFICE


### Details of Inspection:

1. Fire Extengusher not signed
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

### Responsible Party

1. Inspection BB
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

  
Signature of Building  
Representative

MARIA NUNEZ  
Inspector

  
Signature of Administrator

1-22-14  
Date of Compliance



## Safety Inspection Report

Date: 1-24-14 Location: Ware house

### Details of Inspection:

1. Laundry room
2. Shop Area
3. Supply room
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

### Responsible Party

1. \_\_\_\_\_
  2. \_\_\_\_\_
  3. \_\_\_\_\_
  4. \_\_\_\_\_
  5. \_\_\_\_\_
  6. \_\_\_\_\_
  7. \_\_\_\_\_
  8. \_\_\_\_\_
- Everything looks great!*

BB  
Signature of Building  
Representative

\_\_\_\_\_  
Signature of Administrator

Gabriel Lopez  
Inspector

1-24-14  
Date of Compliance



## Safety Inspection Report

Date: 1-27-14 Location: Cairo

### Details of Inspection:

1. Everything looks great!
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

### Responsible Party

- |    |       |
|----|-------|
| 1. | _____ |
| 2. | _____ |
| 3. | _____ |
| 4. | _____ |
| 5. | _____ |
| 6. | _____ |
| 7. | _____ |
| 8. | _____ |

Denise Quaid  
Signature of Building  
Representative

Eric North  
Inspector

\_\_\_\_\_  
Signature of Administrator

\_\_\_\_\_  
Date of Compliance



## Safety Inspection Report

Date: 1-27-14 Location: Alameda

### Details of Inspection:


1. Looks Good.
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_


### Recommendations:

### Responsible Party

1.
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

  
Signature of Building  
Representative

  
Inspector

  
Signature of Administrator

1-28-14  
Date of Compliance



## Safety Inspection Report

Date: 01/17/2014 Location: MAY ROBERTS

### Details of Inspection:

1. - CHECK Classroom 203 Looks Good
2. - CHECK Classroom 210 Looks SAFE
3. - CHECK CAFETERIA Looks Good
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

- |                                  | Responsible Party |
|----------------------------------|-------------------|
| 1. Keep the Hard work Looks good |                   |
| 2. _____                         |                   |
| 3. _____                         |                   |
| 4. _____                         |                   |
| 5. _____                         |                   |
| 6. _____                         |                   |
| 7. _____                         |                   |
| 8. _____                         |                   |

MARIA B. NUNO  
Signature of Building  
Representative

Steve Bishop  
Signature of Administrator

ALBERTO DIAZ  
Inspector

01/17/14  
Date of Compliance



## Safety Inspection Report

Date: 1/17/14 Location: OMS

### Details of Inspection:

1. Looks Great!
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

### Recommendations:

### Responsible Party

1. \_\_\_\_\_
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_
7. \_\_\_\_\_
8. \_\_\_\_\_

Gabrielle Guly  
Signature of Building  
Representative

Lisa Strader  
Signature of Administrator

Shelli Widner  
Inspector

1/17/14  
Date of Compliance