



Safety Inspection Report

Date: 3-10-14 Location: MAY ROBERTS

Details of Inspection:

1. I inspected the East wing and it looks safe
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Mark Miller
Signature of Building
Representative

Ontario Colson
Inspector

Steve Bishop
Signature of Administrator

03/10/14
Date of Compliance



Safety Inspection Report

Date: 3/10/14 Location: Alameda

Details of Inspection:

1. Everything looks Great!!
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

- | | |
|----------|-------|
| 1. _____ | _____ |
| 2. _____ | _____ |
| 3. _____ | _____ |
| 4. _____ | _____ |
| 5. _____ | _____ |
| 6. _____ | _____ |
| 7. _____ | _____ |
| 8. _____ | _____ |

Ronan Gish
Signature of Building
Representative

Kausin Drees
Inspector

[Signature]
Signature of Administrator

3/10/14
Date of Compliance



Safety Inspection Report

Date: 3/11/14 Location: OMS

Details of Inspection:

1. upstairs teachers lounge coffee pots must have a 2 hr shut off
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

- | | Responsible Party |
|--|-------------------|
| 1. <u>Replace coffee pots. - Done. These pots were</u> | |
| 2. <u>used during a special staff</u> | |
| 3. <u>breakfast. They hadn't been put</u> | |
| 4. <u>away yet. They are not pots that</u> | |
| 5. <u>are used on a consistent or daily</u> | |
| 6. <u>basis. Thank you!</u> | |
| 7. _____ | |
| 8. _____ | |

Gabriel Goyko
Signature of Building
Representative

[Signature]
Signature of Administrator

[Signature]
Inspector

3-12-14
Date of Compliance



Safety Inspection Report

Date: 3-11-14 Location: Bus Shop

Details of Inspection:

1. EVERYTHING LOOKS OKEY
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Carlos Nelson
Signature of Building
Representative

Diana Howard
Signature of Administrator

Patricia Miller
Inspector

3-11-14
Date of Compliance



Safety Inspection Report

Date: 3-11-14 Location: Aiken


Details of Inspection:


1. Boiler Room walkway not enough room to walk
2. Box cart
3. Rooms Annex
4. _____
5. _____
6. _____
7. _____
8. _____


Recommendations:

Responsible Party

1. need to clean a walkway custodian
2. look good
3. Rooms look great
4. _____
5. _____
6. _____
7. _____
8. _____


Signature of Building
Representative


Inspector


Signature of Administrator

3-11-14
Date of Compliance



Safety Inspection Report

Date: 3/13/14 Location: warehouse


Details of Inspection:

1. Need put you Tools end Order
2.
3. Put away pipe sticking out in center bay.
4. Back pack blower in front of door
5.
6.
7.
8.


Recommendations:

Responsible Party

1. Clean JP. Antonio
2.
3.
4.
5.
6.
7.
8.


Signature of Building
Representative


Inspector


Signature of Administrator

3/14/14
Date of Compliance



Safety Inspection Report

Date: March 14, 2014 Location: Pioneer

Details of Inspection:

1. Outside / around building
2. Steps / Rails
3. Various classrooms
4. Library
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. _____
2. _____
3. LOOKS GREAT!!!
4. _____
5. _____
6. _____
7. _____
8. _____

Jaime Rhodes
Signature of Building
Representative

Diana Hurst
Inspector

Signature of Administrator

3-14-14
Date of Compliance



Safety Inspection Report

Date: 3/14/14 Location: MT. ST. JAMES

Details of Inspection:

1. Room awesome. Very clean also!
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

1. Keep up the good work!
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Responsible Party

Jodi Wilton-Ross
Signature of Building
Representative

Chad Wilson
Inspector

Signature of Administrator

3/14/14
Date of Compliance



Safety Inspection Report

Date: 3/17/14 Location: CARLO

Details of Inspection:

1. monthly inspection on fire extinguisher
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. Have the Custodian inspect them & Sign off
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Signature of Building
Representative

Sam L...
Inspector

Signature of Administrator

Date of Compliance



Safety Inspection Report

Date: 3/17/14 Location: Dist. Office


Details of Inspection:

1. No Problems Found ☺
2. _____
3. _____
4. _____
5. _____
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

- | | |
|----|-------|
| 1. | _____ |
| 2. | _____ |
| 3. | _____ |
| 4. | _____ |
| 5. | _____ |
| 6. | _____ |
| 7. | _____ |
| 8. | _____ |


Signature of Building
Representative


Signature of Administrator


Inspector

Date of Compliance



Safety Inspection Report

Date: 3/17/2014 Location: OHS

Details of Inspection:

1. CHECK FIRE EXTINGUISHERS in School hall.
2. CHECK Classroom 03 CHEMISTRY
3. Classroom 07
4. Classroom 02
5. 900 HALL
6. _____
7. _____
8. _____

Recommendations:

Responsible Party

1. Looks OK UP date
2. Looks good
3. OK
4. OK
5. OK
6. _____
7. _____
8. _____

Robert S. Gusten
Signature of Building
Representative

ALBERTO DIAZ
Inspector

Signature of Administrator

Date of Compliance