ction Level is 15 parts ber bi	llion (pp	0)		
Fixture Location/Description	Room #	Fixture ID #	Date Tested	
Facilites Office Restroom Faucet	Office	21080703-091BF23A	12/13/2023	2.1
Facilites Office Drinking Fountain	Office	21080703-092WB23A	12/13/2023	ND
Classroom Restroom Faucet	CR	21080703-093BF23A	12/13/2023	1
Classroom Drinking Fountain	CR	21080703-094DW23A	12/13/2023	ND
Classroom Food Prep Faucet	CR	21080703-095KF23A	12/13/2023	1.2
ny fixture testing at or above the act				
nd cannot be returned to service unt	il it has bee	en remediated and passed	d follow-up testing	
ETESTS				