| Fixture Location/Description | Room # | Fixture ID # | Date Tested | |
|---|---------|-------------------|-------------|----------|
| Classroom 212 Faucet | 212 | 21080705-096CF23A | 12/13/2023 | 2.1 |
| Girls Restroom Left Faucet | 213 | 21080705-097BF23A | 12/13/2023 | ND |
| Girls Restroom Right Faucet | 213 | 21080705-098BF23A | 12/13/2023 | ND |
| Boys Restroom Left Faucet | 213 | 21080705-099BF23A | 12/13/2023 | 1.7 |
| Boys Restroom Right Faucet | 213 | 21080705-100BF23A | 12/13/2023 | 3.2 |
| Classroom 214 Left Faucet | 214 | 21080705-101CF23A | 12/13/2023 | ND |
| Classroom 214 Right Faucet | 214 | 21080705-102BF23A | 12/13/2023 | 1/1/1900 |
| Hallway Left Drinking Fountain | Hallway | 21080705-103DW23A | 12/13/2023 | ND |
| Hallway Right Drinking Fountain | Hallway | 21080705-104DW23A | 12/13/2023 | 1/1/1900 |
| y fixture testing at or above the act d cannot be returned to service un | | | | 2 |
| ESTS | | | | |
| | | | | |
| | | | | |